EPA Training Agenda Electrotechnology Applications Center Northampton Community College Bethlehem, PA

<u>Day 1</u>

8:00 a.m. – 8:30 a.m.	Continental Breakfast
	Check In
8:30 a.m. – 9:00 a.m.	Introductions and Review of Training Schedule
	EPA Region III
	Electrotechnology Applications Center
	Baldwin Hardware
	Review of Training Schedule
9:00 a.m. – 10:00 a.m.	Energy Usage Overview
	Industrial Energy Consumption
	Energy Supply and Costs
10:00 a.m. −10:15 a.m.	Break
10:15 a.m. −12:00 p.m.	Energy Consuming Systems and Common ECOs
	Motor Systems
	• Lighting and HVAC
12:00 noon − 1:00 p.m.	Lunch
1:00 p.m. –3:00 p.m.	Energy Consuming Systems and Common ECOs
	Air Compressors
	Boilers and Process Heat
	Pumping Systems
3:00 p.m. − 3:15 p.m.	Break
3:15 p.m. – 4:30 p.m.	Waste MinimizationTraining (EPA)
4:30 p.m. – 5:00 p.m.	Overview of Assessment Tasks
	 Preparing for the Assessment (Review of Baldwin Hardware
	data)
	Assessment Methodology

EPA Training Agenda Electrotechnology Applications Center Northampton Community College Bethlehem, PA

<u>Day 2</u>

9:00 a.m.	Arrive at Baldwin Hardware, Reading, PA
9:30 a.m. – 11a.m	Plant Tour
11 a.m. – 12 p.m.	Brainstorming
12 p.m. − 1 p.m.	Lunch
1 p.m. − 2 p.m.	Data Gathering Session I
2 p.m. − 3 p.m.	Data Gathering Session II
3 p.m. − 4 p.m.	Data Gathering Session III
4 p.m – 4:30 p.m.	Wrap-up Meeting

<u>Day 3</u>

8:00 a.m. – 8:30 a.m.	Continental Breakfast
8:30 a.m. – 9:00 a.m.	Assessment Report Format (EPA)
9:00 a.m. – 10:00 a.m.	Assessment Measures Brainstorming
10:00 a.m. – 10:15 a.m.	Break
10:15 a.m. – 11:00 p.m.	Review of Energy Spreadsheet Tools
11:00 a.m. – 12:00 p.m.	Report Development – Waste Minimization Measures
12:00 p.m. – 1:00 p.m.	Lunch
1:00 p.m. – 3:00 p.m.	Report Development – Energy Measures
3:00 p.m. – 3:15 p.m.	Break
3:15 p.m. – 4:00 p.m.	Information Resources and Open Discussion